

CONTRACTOR TIP

GYPHUM BOARD SHEATHING DAMAGE MUST BE REPAIRED (REPLACED) STUD TO STUD PRIOR TO ANY AIR/VAPOR BARRIER BEING INSTALLED

When the paper face is torn off, the air/vapor barrier will get sucked into the gypsum and not properly adhere.


The air/vapor barrier needs to be fully supported.

Damaged sheathing or sheathing that the face material has been torn off or peeled off is not proper support for the air/vapor barrier – this will cause failure.



Always review your sheathing prior to the installation of the air/vapor barrier & have the sheathing contractor repair stud to stud.

**STUD TO STUD
REPLACEMENT**



BY MR. COREY ZUSSMAN OF PEPPER CONSTRUCTION

air barrier
abaa
association of
america